



DriveMaster 9 Updates - Available Now!

Revisions in DriveMaster V9.1.1700:

- DM critical security updates
- Reinstated the capability to scan 100+ devices on Server Board which has been supported in DM 2015 (v7.x.xxx)
- Added the handling to avoid DM from crashing during Power Cycle when Sanitize is in progress and Microsoft NVMe Driver v19xxx or above is used.
 *There is NO issue if Microsoft NVMe Driver version less than v19xxx (e.g. v17xxx or v18xxx) or OFA NVMe driver is used
- Better handling for memory allocation with HMB
- Added the handling to properly configure PSPA+ Hardware Pins when Power On/Off
- Updated User friendly Information on the returned data for GET LOG w/Persistent Event and IDENTIFY w/UUID List
- Fixed Command DWs in NVM_SETF_ENDRCFG and NVM_SETF_LBASTSINV



- Support TCG Level 0 Discovery for TCG OPAL v2.02
 - Hardware Reset for LOR/DOR in Locking Feature
 - 2. Removal Operation Interrupted in Data Removal Mechanism Feature
 - 3. SSC Version and Minor Version in SSC OPAL2 Feature

TCG CNL Application Note Updates - Available Now!

Revisions in CNL v1.5:

- Added SSC type in each test log
- Removed verifying the values in Column 14h (NamespaceID) and Column 15h (NamespaceGlobalRange) over Global Range in Locking Table
- Updated the checking of Namespace size after new Namespace is created
- Updated LBA settings to better accommodate the different AlignmentGranularity



For more information please visit our **Contact Page** or contact your **ULINK representative**.

Contact us

www.ulinktech.com